General Environmental Incident Summary

Incident: 5438 Date/Time Notice: 6/21/2017 1500 DEM Incident No:

Responsible Party: CHS Inc.

Date Incident: 6/22/2017 Time Incident: 1800 Duration: 0.1 minutes

 County:
 Barnes
 Twp:
 139
 Rng:
 56
 Sec:
 25
 Qtr:

 Lat:
 46.83293
 Long:
 -97.68172
 Method:
 Navigation quality GPS

Location Description: 2942 132ND AVE SE, Valley City ND 58072, Noeske Farms.

Submitted By: Daniel Harjes Affiliation: Safety Manager

Address: 3020 Denmark Ave

City: Eagan State: MN Zip: 55121

Received By:

Contact Person: Daniel Harjes

3020 Denmark Ave Eagan, MN 55121

Distance Nearest Occupied Building: 100 Feet Release Contained: No

Type of Incident: breaking delivery hose connection and didn't have the valve closed

Description of Released Contaminant: Clear Diesel #2

Volume Spilled: 5.00 gallons Ag Related: Yes

EPA Extremely Hazardous Substance: Unknown Reported to NRC: No

Cause of Incident:

Delivery driver delivered diesel into a vertical tank. Upon completion, he disconnected the hose from the tank but didn't have the tank valve closed properly and it sprayed onto him. There was also some amount that went onto the gravel driveway.

Risk Evaluation:

None

of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

None, soil was spread thinly over a large area to expose it to the sun for natural decay.

Action Taken or Planned:

A lot of the fuel was in the form of residue, some saturation. the farmer was there, scraped the surface clean and land farmed the contaminated gravel by spreading it thinly over the surface of the large driveway to decay.

Wastes Disposal Location: Land farmed noted above

Agencies Involved: State Highway Patrol, Local Emergency Manager

Tuesday, October 10, 2017 Page 1 of 2

Updates

Date: 6/21/2017 Status: Reviewed - No Action Required Author: Stockdill, Scott

Updated Volume:

Notes:

Correction to County called in. The County was changed from Cass to Barnes in the database.

Date: 6/22/2017 Status: Reviewed - No Action Required Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary this spill involved a minor amount of fluids that was properly handled by the responsible party. No follow-up is necessary.

Tuesday, October 10, 2017 Page 2 of 2